

ACCIDENT DU 19 JANVIER 2004 – SKIKDA La vérité

- Fact Sheet prepared by California Energy Commission Staff
 - « ... in Skikda, Algeria, a steam boiler that was part of an LNG production plant exploded...
 - …LNG import terminals revaporize LNG back into natural gas, they do not refrigerate natural gas into a liquid. Import terminals, therefore, do not require high-pressure steam boilers.
 - The only components common to both LNG liquefaction plants and import terminals are storage tanks and marine facilities supporting LNG carrier loading or unloading (e.g, pumps and piping). An LNG leak could occur at an import terminal, although terminal design, equipment, and operating procedures are in place to prevent such an event from occurring or escalating.

Rabaska