

Références en lien avec des incidents ou contaminations de la nappe phréatique ainsi que sur le programme de recherche de l'EPA sur la fracturation hydraulique
Demande du BAPE, session du 12 octobre 2010 en après-midi.

Mandat donné par le Sénat américain à l'*Environmental Protection Agency (EPA)*

United States Environmental Protection Agency (2010). Opportunity for stakeholder input on EPA's hydraulic fracturing research study: Study design. Disponible à : http://www.epa.gov/safewater/uic/pdfs/hydrofrac_landscapemodel.pdf.

United States Environmental Protection Agency (2010). Hydraulic fracturing. Disponible à: <http://water.epa.gov/type/groundwater/uic/class2/hydraulicfracturing/index.cfm>.

United States Environmental Protection Agency (2010). Opportunity for stakeholder input on EPA's hydraulic fracturing research study: Criteria for selecting case studies. Disponible à : http://www.epa.gov/safewater/uic/pdfs/hydrofrac_casestudies.pdf.

United States Environmental Protection Agency (2010). Hydraulic fracturing research study. Science in action. Building a scientific foundation for sound environmental decisions. Office of Research and Development, EPA/600/F-10/002, June 2010. Disponible à : <http://www.epa.gov/safewater/uic/pdfs/hfresearchstudyfs.pdf>.

Contamination de l'eau de puits résidentiels

Agency for toxic substances and disease registry (2010). Evaluation of contaminants in private residential well water. Health consultation. Pavillion, Wyoming Fremont County, August 31, 2010. Disponible à : http://www.atsdr.cdc.gov/hac/PHA/Pavillion/Pavillion_HC_Well_Water_08312010.pdf.

United States Environmental Protection Agency (2010). Pavillion area groundwater investigation. Pavillion, Fremont County, Wyoming. Expanded site investigation – Analytical results report. Superfund technical assessment and response team 3 – Region 8. TDD No. 0901-01, August 30, 2010. Disponible à : http://www.epa.gov/region8/superfund/wy/pavillion/Pavillion_GWInvestigationFSP.pdf.

Migration de gaz

Ohio Department of Natural Resources, (2008). Report on the investigation of the natural gas invasion of aquifers in Bainbridge township of Geauga County, Ohio. Division of Mineral resources Management, Septembre 1, 2008. Disponible à : http://s3.amazonaws.com/propublica/assets/natural_gas/ohio_methane_report_080901.pdf.

Pennsylvania Department of Environmental Protection (2010). Public Water Lines to Provide Safe, Permanent Water Supply to Susquehanna County Residents Impacted by Natural Gas Migration. Commonwealth of Pennsylvania, Dept. Of Environmental Protection , September 30, 2010. Disponible à : http://www.portal.state.pa.us/portal/server.pt/community/news_releases/14288.

New-York State – Department of Environmental Conservation (2008). Commissioner's Follow-Up Letter Dated November 13, 2008. Supplemental Information Provided Commissioner Grannis to the NYS Assembly. Disponible à : <http://www.dec.ny.gov/energy/50286.html>

Explosion de puits

VITTITOW, J.G. (2010). Well control incident analysis. EOG Resources Inc. Punxautawney Hunting Club 36H, Clearfield County, Pennsylvania. Disponible à : [http://www.dep.state.pa.us/dep/deputate/minres/oilgas/PunxsutawneyHuntingClub36HWell%20Report/2.BEDROCK ENGINEERING PHC 36H Incident Report.Final.709.pdf](http://www.dep.state.pa.us/dep/deputate/minres/oilgas/PunxsutawneyHuntingClub36HWell%20Report/2.BEDROCK%20ENGINEERING%20PHC%2036H%20Incident%20Report.Final.709.pdf)

Fuite de gaz

British Columbia Oil and Gas Commission (2010). Failure Investigation Report (Wellsite A5-7-77-14) - Piping at EnCana Swan wellsite. Disponible à : <http://www.ogc.gov.bc.ca/document.aspx?documentID=518&type=.pdf>

Autres documents de référence

New York State Department of Environmental Conservation (2009) Draft - Supplemental generic environmental impact statement on the oil, gas and solution mining regulatory program; Well permit issuance for horizontal drilling and high-volume hydraulic fracturing to develop the Marcellus shale and other low-permeability gas reservoirs, Bureau of Oil and Gas Regulation, New York State Department of Environmental Conservation Division of Mineral Resources, Albany, NY, 1-804. Disponible à : <http://www.dec.ny.gov/energy/58440.html>

New York City Department of Environmental Protection (2009) Final impact assessment report: Impact assessment for natural gas production in the New York City water supply watershed, New York City Department of Environmental Protection, and Hazen and Sawyer, Environmental Engineers and Scientists, New York City, 1-51. Disponible à : <http://www.cwconline.org/news/final%20hazn%20sawyr%20report-on-drilling.pdf>

Kargbo, D. M., Wilhelm, R. G., Campbell, D. J. (2010) Natural gas plays in the Marcellus shale: Challenges and potential opportunities, Environmental Science & Technology, Vol. 44, No. 15, pp. 5679-5684. Disponible à : <http://www.environmentalenergylawblog.com/uploads/file/EPA%20Marcellus%20Shale.pdf>