APPENDIX 3

CORE PHOTOS

Phase 1 – Cacouna Energy, Gros Cacouna, Quebec

BH-1



Photo 1







Phase 1 – Cacouna Energy, Gros Cacouna, Quebec

BH-2



Photo 2

 60° fracture filled with calcite







Phase 1 – Cacouna Energy, Gros Cacouna, Quebec

BH-3



Photo 3







S-05-1743, Oct. 2005